



| pos. | qty | benaming                    | description              |
|------|-----|-----------------------------|--------------------------|
| 1    | 1   | Motorsteun                  | Engine support assy      |
| 2    | 2   | Bus                         | Bush                     |
| 3    | 2   | Zeskantbout M10 x 1.25 x 85 | Hex bolt M10 x 1.25 x 85 |
| 4    | 2   | Veerring M10                | Spring lock washer M10   |
| 5    | 1   | Afstandhouder d=5           | Spacer d=5               |
| 6    | 1   | Dynamo 12V-110A             | Alternator 12V-110A      |
| 7    | 1   | Kraagbus                    | Collar bushing           |
| 8    | 1   | Bus                         | Bush                     |
| 9    | 2   | Gegolfde veerring           | Wave spring washer       |
| 10   | 1   | Zeskantbout                 | Hex head bolt            |
| 11   | 1   | Spanner                     | Tensioner                |

| pos. | qty | benaming                    | description                 |
|------|-----|-----------------------------|-----------------------------|
| 12   | 1   | Zeskantschroef M10 x 40     | Hexagon head screw M10 x 40 |
| 13   | 2   | Vlakke sluitring M10        | Plain washer M10            |
| 14   | 1   | Zeskantschroef              | Hexagon head screw          |
| 15   | 1   | Gegolfde veerring M10       | Wave spring washer M10      |
| 16   | 1   | Ring Ø8,4x21x4              | Washer Ø8,4x21x4            |
| 17   | 1   | Snaarschijf                 | Pulley                      |
| 18   | 6   | Zeskantige inbusdop M6 x 30 | Hex socket head cap M6 x 30 |
| 19   | 1   | Veerring M8                 | Spring washer M8            |
| 20   | 1   | Zeskantmoer M8              | Hex nut M8                  |
| 21   | 1   | V-snaar M4                  | V-belt M4                   |
| 22   | 6   | Gegolfde veerring M6        | Wave spring washer M6       |